



- 1. Tie knot 3000mm from end, cut off seal. Push back outer case by 200mm. Hold case and push back slack for 1000mm.
- 2. From rope end, measure 400mm, mark "A" for eye and "B" for standing part.
- 3. Open small hole in case with fid at "B" , pull out core.
- 4. Mark core with tape at "C", opposite "A". Starting at "C", taper core by 50% at end, apply tape. Push slack case back up to "B", until core starts to move. Insert needle at 400mm from "B" to and exit at "A".
- 5. Thread core end through needle eye, and pull through to form eye. Unpick and cut out six yarn ends at a position 5cm from empty case end for taper. Push back the outer case towards the eye to make space.
- 6. Insert needle 200mm from "B". Pull tapered case through rope.
- 7. Pull everything tight, then give splice a hard snatch to bed yarns in position. Cut off protruding ends, smooth down outer case from eye until cut ends disappear.
- 8. If a thimble is required, insert while the eye is being formed, and before the ends are pulled tight.